



MATCH these two as best as possible
 2x 6.79k resistors are better than
 1x 6.81k and 1x 6.82k

Mic in - as per original 1073/1290
 Line in - as per original 1063

BEFORE turn on for the first time
 make sure this trim pot is set
 to COUNTERCLOCKWISE